
FIG. 1 (PRIOR ART)



SUPPLY POWER TO OTHER BLOCKS .201 , 201–3 201 - 5.201-4 SECOND SWITCH FIRST SWITCH THIRD SWITCH FIG. 2 (PRIOR ART) POWER SWITCHING CONTROL SIGNAL 201 - 2201-1 CONTROL POWER SUPPLY SERIAL CABLE VGA SIGNAL .200 S

FIG. 3





FIG. 4







FIG. 5



TURN ON THE POWER OF THE MONITOR AND DISPLAY THE

VGA SIGNALS VIA THE MONITOR

END

~607